



!! URGENT !!

Date: 16 September 2024

Subject: Singapore, Singapore
Paya Lebar (WSAP)
RNP Rwy 02
Cycle 2409

Procedure information incorrect

Jeppesen NavData for cycle 2409, effective 5 September 2024, contains incorrect information for Paya Lebar; Singapore, Singapore (WSAP). Changes in Singapore AIP AMDT 005-24, dated 05 SEP 24 could not be published in time.

RNP Rwy 02: waypoint **LAMA** should be coded as **Fly over**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2410, effective 3 October 2024. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.