

Navigation Database Addendum

AIRAC 2503 – Issue 5

AIP LF MIAC 4 effective 20th March 2025

LF France, Several Military airports

Do not use the following MILITARY procedures, as they are coded with altitudes instead of heights:

LFOA

- TACAN 06-S, TACAN 24-S
- PAR 06-S, PAR 24-S
- ILS/LOC RWY 24
- SID OGAGA 1RE/1RN/1RW

LFBC

- PAR 06-N, PAR 06-N
- TACAN 06-N TACAN 06-S
- ILS/LOC RWY 24
- SID ASKAN, MOTIK, LAPOS, OCEAN, UPODU 4RE/4RW

LFBG

- ILS/LOC RWY 23
- TACAN 23
- SID BG RE 05/23, BG RN 05/23

LFOE

- SID DAMVI

LFTH

- TACAN 05

LFMI

- DEPARTURE RWY 15/33

LFRH

- PAR 07
- ILS/LOC RWY 25

LFSX

- PAR 11
- TACAN 11
- SID SX 2RE/3RW

LFBM

- TACAN 09
- SID BM 1RE/1RW, ENS 1RE/1RW

LFSO

- PAR 02
- SID EPL 2RN/2RS, SO 1RN/1RS

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 5th March 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com