

Navigation Database Addendum

AIRAC 2409 – Issue 13SUP 12/2023 effective 11th April 2023
SUP 04/2024 effective 25th January 2024

FZIC Kisangani Bangoka Intl

Runways 12, 30

RWY 12 temporarily displaced by **750m**. RWY 30 temporarily displaced by **940m**.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Friday, 30th August 2024

All valid FSAs/NDAs are available on $\frac{http://fms-info.lhsystems.com}{for any inquiries, please contact <math display="block">\frac{fms.support@lhsystems.com}{fms.support@lhsystems.com}$