



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

NAVBLUE Reference: 2511-01O

Notification Published date: 22-10-2025

Product Affected: Navigation+

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2511

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

Source: Sudan AIRAC AIP Amd 01/22

NOT IN NAVBLUE DATABASES:

Changes to the direction of the segment KAFIA-ALMAM on airway A410 due to an outstanding state query

is awaiting state information clarification.

Source: South Korea (RKPC) AIRAC AMD 06-24

NOT IN NAVBLUE DATABASES:

LPV Minima and the Path Point have not been included for RNP Y RWY 07 and RNP Y RWY 25 approaches.

is awaiting state information clarification.

Source: Canada (CYAZ) AIRAC AMD 44/24

NOT IN NAVBLUE DATABASES:

RNAV (GNSS) RWY 16 approach has not been added to NAVBLUE databases due to an issue with the CRC value (FAS Data Block).

is awaiting state information clarification.

Source: United Kingdom (EGNX) AIRAC AMD 03/25

NOT IN NAVBLUE DATABASES:

The state has added new approaches for EGNX - East Midlands aerodrome but these new approaches have not been published with multiplier idents and conflict with the approaches



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

already published. Therefore the following approaches have not been included in NAVB:LUE databases:

ILS/NDB(L) RWY 09
LOC/NDB(L) RWY 09
ILS/NDB(L) RWY 27
LOC/NDB(L) RWY 27

is awaiting state information clarification.

Source: Japan (RJOI) AIP AMD 14/25

NOT IN NAVBLUE DATABASES:

RJOI RNAV (RNP) RWY 20 Approach has not been included in NAVBLUE databases due to the unavailability of the waypoint coordinates for IPMER, GURTA, LOBRY, WK001, WK002, SAGPA, WK003, WK004 and PPOPS. The relevant authorities have been contacted.

is awaiting state information clarification.

Source: Bolivia (SLCB) AIRAC AIP Supplement A16/25

NOT IN NAVBLUE DATABASES:

Due to the unavailability of glide slope information the new ILS Z RWY32 approach procedure has not been added to NAVBLUE databases.

is awaiting state information clarification.

Source: USA (KVAD) FAA IFP Information Gateway

NOT IN NAVBLUE DATABASES:

The procedures for MOODY AFB (KVAD) have been withdrawn from NAVBLUE databases due to aerodrome data updates, the procedures will be made available again when the chart updates have been published.

is awaiting state information clarification.

Source: Brazil (SBBI) MAP AIRAC AIP AMD 2511A1

NOT IN NAVBLUE DATABASES:

SBBI VOR Y RWY 18 approach has not been included in NAVBLUE databases due to a discrepancy with the source data for the navaid VOR/DME BCH.



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

is awaiting state information clarification.

Source: Romania (LRSM) AIRAC AIP Amd 12/25

NOT IN NAVBLUE DATABASES:

Due to a discrepancy with the published LPV FAS Data Block, the LPV minima has not been added to the RNP RWY 01 approach.

is awaiting state information clarification.