

!! URGENT!!

Date: 09 October 2024

Subject: Bangkok, Thailand

Suvarnabhumi Intl (VTBS)

Cycle 2410

TWYs E, E19 and E21 status incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2410, effective 03 October 2024, contain incorrect data for Suvarnabhumi Intl; Bangkok, Thailand (VTBS). Thailand AIRAC AIP SUP A52/23, effective 30 November 2023, has been cancelled by NOTAM A2709/24, effective 21 September 2024 at 23:30 [UTC], after 2410 AIRAC cycle data processing due date. Therefore, the following changes, effective 21 September 2024, are not reflected in cycle 2410 data:

- TWY E (between TWY E17 and TWY E21) is open
- TWYs E19 and E21 are open
- Construction Area (southeast of TWY E) is removed

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2411, effective 31 October 2024. Until then this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com **E-mail:** gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.