



!! URGENT !!

Date: 17 March 2025

Subject: Osaka, Japan
Kansai Intl (RJBB)
RNP Rwy 06L
Cycle 2503

Procedure coding incorrect

Jeppesen NavData for cycle 2503, effective 20 March 2025, contains incorrect data for Kansai Intl; Osaka, Japan (RJBB).

RNP Rwy 06L missed approach holding **LILAC** – turn direction should read **RIGHT**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2504, effective 17 April 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Osaka, Japan (RJBB) 22-1 chart dated 14 MAR 25 (effective 19 MAR 2025 1500Z) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

RJBB_2503