



AN AIRBUS COMPANY

RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

NAVBLUE Reference: 2506-04R

Notification Published date: 05-06-2025

Product Affected: Navigation+

AIRAC Cycle: 2506

Effective Date: 12-06-2025

Region: EUR

Country: United Kingdom

Subject: Multiple changes in United Kingdom

Source: MIL AIRAC AMD 06/25

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2506

United Kingdom MIL AIRAC AMD 06/25

BENSON (EGUB):

RWY 01: Length changed from 1826 M to 1825 M, TORA changed from 1826 M to 1825 M, TODA changed from 1926 M to 1925 M, ASDA changed from 1826 M to 1825 M, LDA changed from 1825 M to 1824 M

RWY 19: Length changed from 1826 M to 1825 M, TORA changed from 1826 M to 1825 M, TODA changed from 1862 M to 1861 M, ASDA changed from 1826 M to 1825 M

HEREFORD (EGVH):

Heliport Comms: OPS (134.15, 251.1) call sign changed from Hereford Ops to Heli Ops, OPS (134.15) Service Provider changed from secondary to primary and OPS (251.1) Service Provider changed from primary to secondary.

LEEMING (EGXE):

RWY 16/34: Length changed from 2291 M to 2292 M, TORA changed from 2291 M to 2290 M, ASDA changed from 2291 M to 2290 M, LDA changed from 2291 M to 2290 M.

MARHAM (EGYM):

ILS 23 IMR: LOC BRG changed from 235° to 234°



AN AIRBUS COMPANY

RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

WARTON (EGNO):

Airport record: Mag VAR changed from 1°W to 0°E,

RWY 07: MAG BRG changed from 72° to 71°

RWY 25: MAG BRG changed from 252° to 251°

ILS 25 IWQ: LOC BRG changed from 253° to 251°, STAT DEC changed from 1°W to 0°E

ILS DME 25 IWQ: STAT DEC changed from 1°W to 0°E

WATTISHAM (EGUW):

ILS 23 IWAT: LOC BRG changed from 232° to 231°

These changes will be incorporated in NAVBLUE databases for cycle 2507